



Steam Energy Recovery Survey




Excessive steam trap leak on Unit # 4190



Steam Trap Samples show proper operation.

Faulty Valves and Traps Allow Excessive Energy Loss!



The Thermal Image locates the external insulation gaps allowing excessive heat loss on external steam and/or water lines.